

**Amendments to the Specification:**

On page 23 of the specification, please replace the paragraph beginning at line 13 with the following paragraph:

In another alternative (~~not shown~~ see FIG. 20), the lid 910 has a plurality of retaining members 951 in the top wall 912. For example, a first retaining member 951 is positioned at nine o'clock and a second retaining member 951a is positioned at three o'clock, while the drink opening 928 is positioned at six o'clock. This means the first and second retaining members 951, 951a are in an opposed positional relationship in the top wall 912. As another example, the retaining members 951, 951a are positioned in the top wall 912 at roughly forty-five degrees from the drink opening 928. In each of these examples, the first and second retaining members 951, 951a are equivalently distanced from the drink opening 928. However, the first and second retaining members 951, 951a could be distinctly positioned in the top wall 912 with respect to the drink opening 928. Thus, the first retaining member 951 is positioned at seven o'clock and the second retaining member 951a is positioned at roughly three o'clock.